

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Figure 1

H₂ Desorption Amounts for AR026

■—AR026 - MA w/ Heptane & Graphite (2 hr) ♦—AR026 - MA (48 hrs)




Figure 2

Figure 3B





Figure 3A






Figure 4





Figure 5

Figure 6



XRD from MS+MA AR3 powder
showing amorphous +
microcystalline MgNi




Figure 7B

[A098A.RAW]MSAR003-042502Rita
XRD from MS ribbon before MA
showing Mg_2Ni , $Mg(Ni,Co)_2$
polycrystals.




Figure 7A

H₂ Desorption Amounts for AR031 Material (4 hour Desorption Time)

A-AR031- 2 hr Grind w/ Heptane and Graphite in Glove Box, Pressed in Ar - Coated w/ Pd (Cycle 2)
B-AR031- 2 hr Grind w/ Heptane and Graphite in Glove Box, Pressed in Ar - Coated w/ Fe (Cycle 2)
C-AR031- 2 hr Grind w/ Heptane and Graphite in Glove Box, Pressed in Ar - Coated w/ 10Å Pd & 10Å Fe
D-AR031- 2 hr Grind w/ Heptane and Graphite in Glove Box, Pressed in Ar - Coated w/ 100Å Pd & 100Å Fe (Cycle 2)




Figure 8A

H₂ Desorption Amounts for AR026 and AR031
2 hr Grind w/ Heptane and Graphite in Glove Box, Press in Ar
(4 hour Desorption Time)





Figure 8B

Hydrogen Desorption in Mg-based AR Material



- * Pd-layer only makes limited contribution to H-desorption due to low H-content
- * The surface of Mg-rich storage phase may be the main area to recombine the H-atoms.

Figure 9

Absorption Rate Measure MSAR003, 26, 30, and 31 Material at 90°C





Figure 10

Figure 11

Cycling Stability at 200°C






Figure 12




Figure 13




Figure 14




Figure 15

200°C PCT Measurement Result

AR026: $Mg_{55}Ni_{36}Co_3Mn_6$

AR003: $Mg_{52}Ni_{39}Co_3Mn_6$

AR037: $Mg_{47}Ni_{44}Co_3Mn_6$

AR038: $Mg_{42}Ni_{49}Co_3Mn_6$




Figure 16

**Plateau Pressure Comparison at 200°C
Based on Magnesium Content**




Figure 17

8/20/2003

Improvement of Low-Temperature MgNiCoMn Alloy Processing

Reduced Carbon Contamination





Figure 18

Figure 19

**Glove Box Protection
(Hydrogen Absorption at 90°C)**



Hydrogen Storage of AR003 at 90°C




Figure 20




Figure 21

Effect of Ag at 90°C




Figure 22

Various Catalysts for Hydrogen Absorption at 90°C




Figure 23